

# Oil Field Environmental Incident Summary

**Incident:** 20160926094631 **Date/Time of Notice:** 09/26/2016 09:46

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** REDMOND 27-2932H

**Field Name:** CLEAR WATER

**Well File #:** 22931

**Date Incident:** 9/25/2016 **Time Incident:** 11:30

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 157

**Rng:** 89

**Sec:** 29

**Qtr:**

**Location Description:** Majority of liquids stayed onsite and the location was holding a lot of storm water from the rain events. The perimeter berm was breached off to the south with water. A message was left with landowner.

**Submitted By:** Danielle Dupay

**Received By:**

**Contact Person:** Danielle Dupay  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	78	Barrels	60	Barrels	78	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/3/2017

**Clean Up Concluded:** 10/17/2016

**Risk Evaluation:**

N/A

**Areal Extent:**

offsite area of 50'x50' to south

**Potential Environmental Impacts:**

N/A

**Action Taken or Planned:**

The PW and storm water liquids onsite were removed with vac truck. The lines will be replaced with poly. The offsite area will be potholed with a hydrovac to determine if offsite areas are affected. Field tests and soil samples will be conducted. Any contaminated material will be disposed of. Further information found will be added into the follow-up report.

**Wastes Disposal Location:** Water onsite was pushed back into the water tank onsite and solids will be disposed of at Clean Harbors.

**Agencies Involved:**

**Updates**

---

**Date:** 9/26/2016    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

---

**Date:** 10/10/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 16:09, 10/10/2016.

Excavation 4' by 75', down 2' below surface grade to the south of the location. Some standing water on location and in excavation. Contacted company and informed contact that the excavation was filled with water. They took samples and were waiting on results before backfilling. They are going to use a vac truck to remove the water in the excavation.

More follow-up is necessary to ensure cleanup.